



AIRCRAFT ACCIDENT REPORT (Ref. N0 3/2017)

Report on the Gear-up Landing Accident (14th September 2017)

This investigation has been conducted in accordance with
*Annex 13 to the ICAO Convention on International Civil
Aviation, EU Regulation No 996/2010 and
The Civil Aviation (Investigation of Air Accidents and Incidents) Regulation; Legal
Notice 16 of 2013.*

Under these Regulations, the sole objective of the investigation of an accident or incident is the prevention of accidents and incidents in the future. It is not the purpose of this investigation to assign fault or blame and the reporting process should not be used to determine liability.



ACCIDENT REPORT

Aircraft Type and Registration:	Piper PA-34-200T Seneca II, 9H-AEB
No & Type of Engines:	2 Continental Motors Corp TSIO-360-RB piston engines
Year of Manufacture:	1978 (Serial no:)
Date & Time (UTC):	14 th September 201: 18.07
Location:	Luqa Airport Malta RWY23/05
Type of Flight:	Training Flight
Persons on Board:	Crew - 2
Injuries:	Crew - None
Nature of Damage:	Damage to both propellers and superficial damage to underside of the fuselage and engine cowlings
Commander's License:	Instructor License.
Commander's Flying Experience:	5,300 hours. Multi-Engine time; 934hours of which 60 were on the Seneca II
Training Pilot Flying Experience	220 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot and further investigations by BAAI.

1.0 Synopsis

The crew was on a training flight performing circuit work, including touch-and-go and single-engine approaches and landings. Flying from the left seat was the student pilot who had previously logged approximately 4 hours Multi-Engine time on a different type of aircraft with a different flight school.

On this approach the crew landed with the landing gear in the up position. A combination of factors may have contributed to this accident, including the fact that both pilots were relatively inexperienced in this type of aircraft.

2.0 History of the flight

The aircraft landed on RWY 23/05 with the landing-gear in the up position. The two pilots evacuated the aircraft using the normal entry/exit door. Emergency services attended, but there was no fire or need for assistance.




Fig. 1

3.0 Technical information;

Main Landing Gear extension/retraction system

3.01 The Seneca II uses hydraulic power supplied by a single reversible electric pump/ reservoir to raise and lower the landing gear. Normal gear selections are made using a switch on the instrument panel labelled "up" and "down".

3.02 If hydraulic pressure is lost, all three gears should drop under their own weight. The landing gears are designed to free-fall if the emergency extension valve is pulled.

3.03 The main gear down-lock mechanism comprises a conventional over-center side-stay, kept in lock by a pair of hooks engaging on a pin.

3.04 Engagement of the hooks also actuates a micro-switch to illuminate the associated *down-and*

locked green light in the cockpit. Under normal operations (*powered extension*), the final movement of the actuator engages the hooks, but in a free-fall extension, a spring is used to engage the down-lock hooks. If any one of the three gears fail to down-lock, a gear-unsafe red warning light illuminates.

4.0 Landing-Gear Indications and Aural Warnings.

4.01 When the LANDING-GEAR is fully down, *three green lights* indicate that the LANDING GEAR is down and locked, and a convex mirror on the left engine nacelle enables the pilot to confirm the position of the gear. If the “NAV Lights” are switched on, the gear lights are automatically dimmed. A “RED WARNING” light illuminates on the instrument panel if the landing gear is not fully locked in the selected position.

4.02 A micro switch incorporated in the throttle quadrant activates a warning horn under the following conditions:

- Gear up and manifold pressure reduced below 14 inches on either one or both engines.
- Gear selector switch in the UP position when the aircraft is on the ground.

5.0 Inspection of the Aircraft and Official Documents.

- Following the accident, the aircraft was taken to a hanger and placed on hydraulic jacks. Here the aircraft was raised sufficiently off the ground to allow the necessary test and maintenance to be carried out safely. As part of the investigation, the Aircraft systems and operation of the Landing-Gear were carried out and found to be fully functional. The aircraft electro-hydraulic pump as well as the free-fall emergency extension operated normally.
- Aural and visual warning systems were tested and found to operate according to the official Piper Seneca technical manual.
 1. The 3 green lights on the instrument panel came on when the landing gear was extended down and locked.
 2. The aural warning was tested and found to operate according to the Piper Seneca Technical Manual.



Fig.2
3 Greens on the Landing-Gear down and locked indication.

5.1 Visible damage.

- Both propellers suffered extensive damage.
- Both engines and associated systems must be thoroughly checked for damage sustained during the accident.
- Scratch marks on various parts of the underside of the fuselage.

Fig.3



Damaged Port and Starboard Propellers

5.2 Maintenance Records and Legal documents.

Maintenance records were checked and found to be correct. Maintenance carried out according to schedule and recommended standards as stipulated by law and Piper Seneca II standards. Legal documents found to be compliant with the Maltese Law.

6.0 Checklist Format.

6.01 Basically, there are two checklist formats.

- The flow-checks method (Do and read). This requires that the checklist items are first accomplished from memory and then the checklist is reviewed to ensure that all items contained in the checklist have been completed. The items are read from the checklist and physically or visually confirmed.
- The self-challenge/response method (Read and do). This requires that all items on the checklist to be sequentially completed and then checked for correct position of associated switches and system operation. The checklist should be read aloud.

6.02 Conventional thinking is that the SELF-CHALLENGE/RESPONSE format should be used for all checklist groups **prior** to RWY and T/O procedures, while the FLOW-CHECK format should be applied to RWY and T/O checklist groups as well as airborne groups including the pre-landing checklist.

7.00 Interview with the crew.

The crew was interviewed on the 26th of October at the BAAI office Valletta.

The importance of human factors in aviation, particularly pilot error, has long been known, but few people seem to understand how important it is to be mentally and physically prepared (*well rested*) for a flight. This is highlighted by the fact that about 80% of aviation crashes and 50% of aviation

incidents are attributed to pilot error. Statistically, the improper use, or the non-use, of the normal/abnormal checklist by flight crews is one of the most common pilot errors.

7.01. *Pre-flight preparation.* The instructor gave a detailed description of how the training session was organized. He said that; weather at the airport, NOTAMs, weight and balance, performance calculations and the exercises to be accomplished during the flight, were reviewed.


7.02 The student pilot had already logged approximately 4 hours Multi-time on another type of aircraft consequently he was only scheduled to fly just 2 hours on the Seneca. According to regulations, six hours of multi time are enough to qualify for the multi engine rating.

7.03 The instructor said that he was not satisfied with the fact that the student pilot was only required to fly the Seneca for just two hours. In his opinion, more time (more than 2 hours) on type is necessary for a pilot to become proficient on a new type of aircraft, especially if the pilot is an inexperienced student pilot.

7.04 The instructor remarked that the fact that he was required to achieve what normally takes more than 2 hours to accomplish, has distracted him from his primary duties; .

7.10 To qualify for the Multi-Engine Rating, a pilot must demonstrate that he can safely fly a “*single engine approach and landing*”. A pilot should thoroughly understand the aerodynamic problems which surround asymmetric flight and perform, without hesitation and in a deliberate manner, the actions that must be accomplished in the event of an engine failure. (Ref fig 4 & 5)

Fig 4



Note. Although an engine failure is not considered to be a catastrophic failure in a multi engine aircraft, it can be very demanding on the crew – something which significantly contributed to this accident. As can be seen from the flow chart below, situational awareness is essential to gain control of the aircraft.




Fig.5
A typical engine failure flow chart.

8.00 Standardization and cockpit safety

The basis of pilot standardization and cockpit safety is the checklist which is purposely produced by aircraft manufacturers to guard against human error. Performing checklist actions by recall only, without consulting the aircraft's checklist is never advisable as it will lay to waste a valuable cockpit resource.

The crew's failure to complete the before-landing checklist or to complete the checklist according to the correct procedure (ref item 6.01) may have contributed to this accident. The question is; what distracted the crew and did the crew cut corners by not sticking to procedures

8.02 When interviewed by BAAI, neither pilot was able to explain what actually happened during the latter stages of the approach onto RWY 23/05, nor why it had happened. ATC was never informed that they had a problem which means that the crew was completely unaware that the undercarriage was still in the up position.

The landing gear is mentioned in the following Checklists;

- Pre-Landing Checklist
- Single Engine land

- Final Vital Items.

. Reference: Appendix "A" of this report

8.03 During the interview, the following points were noted:

1. The student pilot was relying on his instructor's advice to fly the aircraft according to the Seneca recommended procedures. *Note: This was the student-pilot's first flight on the Seneca II.*
2. The instructor has approximately 5300 flying hours and has flown as an instructor for a foreign airforce on jet as well as propeller aircraft. His total flying time on the Seneca II was approximately 60 hours..
3. The crew did a proper briefing, but because of delays on the ground and lost time in the air, they found themselves struggling to finish the whole session in just two hours.
4. There was some confusion on the flight deck as to who was expected to do what.
5. Due to Goal fixation, the crew was unsure if the *approach checks* were inadvertently omitted, done by recall or how and who performed the checks.
6. In the briefing room, the instructor did an in-depth takeoff, cruise and approach/go-around briefings and also a detailed discussion about the exercises to be completed during the flight.

9.0 Conclusion.

When the aircraft was checked in the hanger, BAAI found no evidence of "pre-impact mechanical malfunctions or anomalies" that would have hindered the plane's normal operation. This means that there were no mechanical malfunctions that could have contributed to the accident. CCTV footage shows the student pilot performing a near perfect landing, which explains why the aircraft suffered only minimal damage and confirms that the aircraft was completely under control throughout the approach and landing.

During the interview, the crew said that felt that they were under pressure to perform all the required exercises in just 2 hours. This may have created a situation where time management became more important than flight management and safety. A simulated engine failure is by no means an easy exercise therefore enough time should be devoted to perform all actions correctly, including consulting the official checklist after gaining full control of the aircraft and when time permits.

The final conclusion is that the crew may have fallen victim to one or more of what is referred to in aviation as the "FATAL FIVE". (*Reference Flight Safety article by Kreisha Ballantyne*). It is highly probable that items (1) Task Saturation and (2) Task/ Goal Fixation, which causes all cognitive capacities to be focused on one task exclusively, may have reduced the crew's capacity to accomplish what they normally perform efficiently and safely.

The Fatal Five.

1. Task Saturation.

2. Task/Goal Fixation. (Fixation causes all cognitive capacity to be focused on one task.)
3. Attribution Error.
4. Vigilance Decrement.
5. Confirmation Bias.

It is good airmanship to remember that paying attention to detail and performing all actions according to the recommended procedure without cutting corners, may mean the difference between a flight that ends successfully and one that ends in tragedy.

10.0 Recommendations

1. Use the official checklist and follow it accurately - it is a reliable cockpit resource.
2. Develop the objective to comply with safe operating practices and act upon it especially when under pressure.
3. Do not substitute safe practices with your own shortcuts.
4. Know when your resolve to conform may weaken as this may be the first indication that the aircraft is ahead of you.
5. Plan into your mind-set how you will overcome that weakness and stick to it.

Capt. Frank Zammit.

Chief Investigator of Air Accidents.

Appendix A

Seneca II Normal and Abnormal/Emergency Check-List.

PREFLIGHT CHECK		
COCKPIT PREPARATION Aircraft Documents----- Stowed Parking Brake----- ON First Aid Kit----- Stowed Fire Extinguisher----- Check Gear Selector----- Down Gear Emergency Selector-----In & Guarded Battery Master Switch----- On Landing Gear Lights----- Three Greens Fuel Quantity----- Adequate + Reserve Battery Master Switch----- OFF Magneto Switches----- OFF Mixture----- Idle cut-off Trim Indicators----- Neutral Flaps----- Check Operation Flying Controls----- Full Free Correct Movement Empty Seats----- Fasten Belts Cross Feed Drains----- Operate OUTSIDE CABIN Battery Master Switch----- ON Exterior Lights----- On / Check/Off Stall Warning Vanes----- Check Pitot Heat----- Check (Max 3 min ground ops) Battery Master Switch----- OFF Windshield----- Clean Baggage and rear door ----- Secure and Locked	When Engine Starts Throttle-----Retard and Set 1000 / 1200 RPM Oil Pressure N ^o 1---Check (Rise Within 30 Secs) Alternator N ^o 1----ON and Check (Max 60 Amps) Gyro Pressure---Check / Warning Indicator OFF Alternator N ^o 1----- OFF Starting Eng N^o 2--- Repeat procedure for N^o 2 Alternators---Both ON check balance approx 15 AMP each	Alternators Output-----Check Gyro pressure----- 4.8 – 5.1”Hg Throttle-----Close/Check Idle (700 –900 RPM) Throttle----- 1000 RPM Pressures & Temperatures----- Check Fuel Flow-----Check (Usually 5 –7 GPH) De-Icing Boots----- Check (Inflate (6 secs) Suction Drops 6”) Propeller De-Icing----- -Check Twice On & Off Annunciator Panel----- Test
BEFORE STARTING ENGINE	AFTER START CHECK LIST	BEFORE TAKE OFF CHECK
External Checks----- Completed Main Doors----- Closed & Latched Seats/Belts/Harnesses-----Adjusted and Set Parking Brakes----- SET Alternate Air Controls----- OFF Circuit Breakers----- IN Cowl Flaps----- Open Battery Master Switch----- ON Avionics Master & Radio----- ON ATIS Copied and Start-up Clearance--Obtained Altimeter----- Set with local QNH Radio & Avionics Master----- OFF Battery Master Switch-----If no clearance OFF	PFD----- ON Electrical Trim----- ON/Check/Set MFD----- Check units Avionics Master Switch----- On Intercom----- Check On & Volume Set Comms/Navs 1&2 /DME /ADF ----- On Transponder ----- Standby Left Fuel Selector --- Check Shutoff / X-Feed /ON Right Fuel Selector -Check Shutoff /X-Feed /ON Avionics -----CHECK & SET for departure Markers ----- On A/P----- ON / Check / Disconnect (red button) Cabin Heat/Defrost----- Check Air Intake----- Open Heat/Fan Switch ----- Check Defrost Switch-----Check Fan----- As required Clock ----- Set (UTC) Stop Watch----- Wound Nav Lights----- As req. Fuel Pumps----- ON & OFF Check Flight Instruments----- Set and Check Radios----- Intentions & request taxi	Trimmers----- Set / (T.O. pos.) Throttle Friction----- Set Mixtures----- Rich Fuel Selectors----- On Check Content Propellers-----Fully forward(Max RPM) Auxiliary Fuel Pumps----- Off Flaps----- (As required) Set for T.O. Cowl Flaps----- Set (1/2 or fully open) Alternate Air----- Off Cabin Heater/Defrost-----As Requested Seat Belts/Seat Back-----Secure/Erect Main Doors----- Latched & Closed Flying Controls----- Full/Free Movement Auto Pilot----- Confirm Off Departure Clearance----- Copied TO and Departure briefing -----Completed Altimeters-----QNH set / Check vs elevation Avionics-----Confirm RAD/NAV Engine Instruments----- Check Propeller De-Icing----- As Required Vent Fan----- Off Take Off ----- Clearance
STARTING ENGINES	TAXI CHECKLIST	RWY ITEMS
Battery Master Switch----- confirm ON Beacon light (Fin light)----- ON Auxiliary Fuel Pumps----- OFF Avionics Master----- OFF Starting Engine N^o 1 Fuel Selector N ^o 1----- On Mixture N ^o 1----- Full Rich Propeller N ^o 1----- Full Forward Throttle N ^o 1----- Half Travel Magnetos Switches N ^o 1----- On Prime----- (3 Secs Warm, 6 Secs Cold) Propeller Area----- Clear Starter----- Engage	Look outside and Check----- (Right & Left Clear) Parking Brake----- OFF Brakes & Steering (Both Pilots)----- Check Flight Instr. (TC, HIS, Compass, AH, RMI) Check	T.O. Time ----- Noted Flaps----- Check Transponder----- Set ALT Mode Landing, Recognition, Anti-Collision Lights--On Pitot Heat-----As Required (Max 3 Min on gnd) RWY HDG----- Check when aligned
POWER CHECKS	AFTER T.O. CHECK LIST	CRUISE CLIMB CHECK LIST
Position----- Into Wind & Area Clear Parking Brake----- On Temperatures & Pressures----- Check Cowl Flaps----- As Required Fuel Selectors----- ON Throttle----- 1200 RMP Commence With Left Engine Checks Propeller Feather-----Check Max. 300 RPM Throttle----- 1900 RPM Propeller Control----- Exercise Propeller----- Check Governor Alternate Air----- On Then Off Magnetos----- Check 150/50	Gear-----Up (Max Retraction Speed 107KTS) Flaps----- Retract Above 200’ AGL Power----- Set 32”/2450 RPM Landing lights----- OFF Altimeters----- Set / Cross Checked Icing----- Check Radio Aids----- Identify If Required	Climb PWR----- Set 32” / 2450 RPM Pitch down ----- (Speed 100 / 110 KIAS) Cowl Flaps----- As Required ATC Liaison to proceed as VFR / IFR

CRUISE CHECKS	Trimmers----- Neutral Cowl Flaps----- Open Radio / Nav Equipment----- As Required	STARTING ENGINE WHEN FLOODED
Cruise Power----- Set as Required Mixtures----- Lean ROP EGT----- check max 1550° F Engine Instruments----- Check Cowl Flaps----- As Required Icing----- Check OAT FREDA CHECKLIST	SHUTDOWN CHECKLIST	Mixture----- --Idle Cut Off Throttle----- FULLY FORWARD PROPELLER----- FORWARD Master Switch----- ON Magnetos----- ON Auxiliary Fuel Pump----- OFF Propeller Area ----- Clear Starter ----- Engage When Engine start: Throttle----- retard Mixture ----- Advance slowly
DESCENT CHECKS	Parking Brake----- ON Throttles----- 1200 RPM Avionics & Avionics Master Switch----- OFF Heater / Fan----- 2 min then OFF Ammeters----- Check (Less Than 10 AMPS) Exterior Lights - except ACL (Fin) Light----- OFF Check -----3 Mins Have Elapsed Since Landing Mixtures----- I.C.O Magnetos----- OFF Anti Collision Light (Fin)----- OFF Interior Lights----- All OFF Battery & Alternators----- OFF Control Wheels----- Secure With Seat Strap DURING CLIMB IN HOT WEATHER CONDITIONS, IT MAY BE NECESSARY TO USE LO AUXILIARY FUEL PUMP FOR VAPOR SUPPRESSION AVOID CONTINUOUS GROUND OPERATION BETWEEN 1700 – 2100 RPM IN CROSS / TAIL WIND OVER 10 KT AVOID CONTINUOUS OPERATIONS BETWEEN 2000 RPM and 2200 RPM ABOVE 32" MP * PFD default units: * Alt/Vs - feet * Spd -kts * Nav angle -magnetic * Distance - Nm	STARTING ENGINE IN COLD WEATHER
APPROACH CHECKLIST	Radio/Nav Equipment----- Set / Identified H.S.I./R.M.I & Compass----- Cross Checked Altimeters----- Set/Cross Checked Approach Briefing ----- Completed Minimums----- Set MFD	Props----- Turn through by hand (3 times) Fuel Selector----- Mixture----- Full RICH Throttle----- full FORWARD Propeller Control----- full FORWARD Master Switch----- ON Magnetos----- ON Auxiliary Fuel Pump----- On low boost Starter----- Engage Primer----- On for 3 seconds Throttle----- full FORWARD to full AFT Primer----- ON & OFF every 3 sec.
PRE LANDING CHECKLIST	V-speeds for SENECA II Vso61 KTS Vs163 KTS Vmca66 KTS Vr (Short Field).....71 KTS Vr (Normal).....80 KTS Vx76 KTS Vy89 KTS Vyse.....89 KTS Vsse.....76 KTS Cruise Climb.....32' / 2450rpm ... 110 KTS Holding speed.....120 KTS Downwind 10° Flap & Gear down 100 KTS Base 25° Flap.....95 KTS Final 40° Flap.....85 KTS Intermediate Apch Segment120-100 KTS Final Apch Segment 25° Flap.....95 KTS Vne195 KTS Vno.....163 KTS Va135 at 4407 lbs / 121 KTS at 3068 lbs Vfe 10°.....138 KTS Vfe 25°.....121 KTS Vfe 40°.....107 KTS Vle.....129 KTS Vlo Extending.....129 KTS Vlo Retracting.....107 KTS Demonstrated X-WIND 17 KTS	STARTING ENGINE WITH EXTERNAL POWER SOURCE
Seats/Seat Belts----- Erect/Secure Fuel Selectors ----- ON Rudder----- Neutral Flaps----- -Set Cowl Flaps----- Open Mixtures----- Rich Propellers----- 2450 RPM Brakes----- Off Landing Gear----- Down / below 129 KIAS (three green one on the Mirror) A/P ----- OFF Landing Lights ----- ON	FINAL VITAL ITEMS	Master Switch----- OFF All electrical equipment----- OFF Terminals----- Connect External Power plug----- Insert in Fuselage Proceed with normal start: Throttles----- lowest possible RPM External power plug----- disconnect from fuselage Master Switch ----- ON (Check ammeter) Oil Pressure----- Check
FINAL VITAL ITEMS	Mixtures ("Reds")----- Full Rich Propellers ("Blues")----- Full Forward Undercarriage----- 3 Greens	
AFTER LDG CHECKLIST	Landing Time----- Noted Flaps----- Up Transponder----- STBY Pitot Heat----- Off Recognition Lights----- Off Landing Lights----- As Required Propeller De-Ice----- Off Air Intake----- Open Heater/Fan Switch----- Fan Defroster----- As Required	

ENGINE FIRE ON GROUND	<p>Before feathering & securing Inop. Engine: Fuel Flow ----- Check (If deficient press.)--Aux. Fuel Pump HI BOOST (If power is not restored)- Aux. Fuel Pump OFF Fuel Quantity----- Check Alternate Air----- ON Mixture, T & Ps and Magnetos -----Check Re-start----- Try</p> <p>Below 66 Kts Rudder -apply to maintain heading /against turn Throttles (both engines)-----retard to stop turn Pitch down---- to increase speed above 66 Kts Above 66 Kts (pitch to maintain > 66 Kts) Operative engine---increase pwr as required Airspeed-----pitch for Blue Line (89 kts) Drag ----- minimise (Ldg Gear / Flaps) If Altitude permits a restart may be attempted If restart fails or altitude does not permit: Inop. Eng. Prop-----Feather Inop. Eng-----Complete Eng. Sec. Proc. Cowl Flaps (Operative Engine.) -----as required</p>	EMERGENCY GEAR EXTENSION
<p>If Engine has Not Started: Mixture----- I.C.O Throttle----- Open Fully Starter----- Operate If Engine Has Started: Engine----- Keep Running If Fire Continues, After A Few Seconds Throttles----- Closed Mixtures----- I.C.O. Fuel Pumps----- Off Fuel Selectors----- Off Magnetos----- Off Brakes----- Set Battery Master Switch----- Off</p>		<p>Check Before Extending gear manually: Battery Master Switch-----ON Circuit Breakers----- IN Alternator Output----- NORMAL Navigation Lights ----- OFF (Daytime) Airspeed----- Below 85 KTS Gear Selector----- GEAR DOWN Gear Emergency Knob-Release Guard & Pull Gear Indicator Lights-----Check 3 Greens Red Unsafe Light Out Nose Wheel Position Check by the Mirror</p>
ENGINE FIRE IN FLIGHT	<p>UNFEATHERING PROCEDURE AND STARTING CHECKLIST</p> <p>Fuel Selector (inop engine)----- ON Throttle-----Set ¼" Open Propeller Control--forward to cruise RPM pos. Mixture----- Rich Auxiliary Fuel Pump (inop engine) -----OFF Magneto Switches----- ON Starter-----engage until prop. Wingmills Throtte-----reduce power until engine is warm Alternator----- ON If engine does not start----- prime as required</p>	EMERGENCY DESCENT
<p>Affected Engine: Fuel Selector----- Off Throttle----- Close Propeller----- Feather Mixture----- I.C.O. Heater----- Off Defroster----- Off If fire continues and terrain permits----- Land Immediately</p> <p>Note : DONOT Attempt A Restart Following An Engine Fire</p>		<p>Throttles----- Closed Propellers----- Full Forward Mixture-----As Required for smooth operation Landing Gear----- Extend Flaps ----- As required Cowl Flaps----- As required</p>
ENGINE FAILURE MEMORY ITEMS		TRIM RUNAWAY
<p>AUTOPILOT -----D ISCONNECT FLY THE AEROPLANE.....PITCH FOR BLUE LINE PUSH RUDDER TO MAINTAIN HEADING (and some aileron to same side) POWER-UP.....MIXTURES FULL RICH P ROPELLERS FULL FORWARD TH ROTTLES ADVANCE, Max 40" CLEAN-UP (minimise drag).....LDG GEAR UP FLA PS RETRACT IDENTIFY.....DEAD FOOT is DEAD ENGINE VERIFY----- THROTTLE DEAD ENGINE CLOSE FEATHER (restart not feasible or when failed) PROPELLER DEAD ENGINE FULL FEATHER MIXTURE DEAD ENGINE.....IDLE CUT-OFF</p>		<p>Autopilot ----- Disconnect Trim -----Disconnect Trim and Autopilot circuit breaker-----OFF Re-Trim ----- manually</p>
SECURE DEAD ENGINE AFTER FEATHERING	<p>ELECTRICAL FAILURES</p> <p>Double Alternator Failure Field Circuit Breakers----- Check/Reset Alternator Switches Off (both) then turn ON one at a time while observing ammeter Alternator showing Least (but NOT ZERO) amps. And turn it switch ON If power is not restored: Check circuit breakers And reset once if required. Electrical Load----- As Required If Output Not Restored: Battery Master Switch-----Off For 6 Sec Min If Failure Persists Battery Only Remains Max. Of 30 Mins. Land ASAP. Extend Gear By Emergency System.</p>	PROCEDURES IN ICING CONDITIONS
<p>Fuel Selector Dead Engine.....SHUT OFF Mixture Dead Engine.....(Verify) I.C.O. Cowl Flap Dead Engine.....CLOSE Magnetos Dead Engine..... OFF Alternator Dead Engine.....OFF Fuel Pump Dead Engine.....(Verify) OFF Engine Instruments Live Engine.....CHECK Cowl Flap Live EngineOPEN Electrical LoadREDUCE Power Live Enginewhen feasible 32" / 2450 RPM Gyro PressureCHECK Fuel Selector Live EngineConsider CROSS-FEED</p>		<p>Pitot Heater----- Confirm On Windshield Heat----- On Propeller De-Icer----- On Windshield Defroster----- On Select Air Intake ----- OPEN Heat / Fan Switch ----- HEAT Thermostat Control ----- Hot Defrost Switch ----- ON De-Icing Boots-----On ¼ - ½" Ice Build If Required: Alternate Air Controls----- ON Alternate Static Source----- Select</p>
ENGINE FAILURE DURING FLIGHT	<p>Single Alternator Failure Field Circuit Breaker-----Check/Reset Ammeter/Warning Light----- Check Alternator Switch----- Cycle If Output Restored: Electrical Load----- As Required</p>	SINGLE ENGINE LANDING
<p>Airspeed-----89KTS Minimum (Blue Line) Trim----adjust 5° bank toward operative engine Memory items----- Completed</p>		<p>Approach speed----- 95 KTS Mixture ----- Full Rich Inop. Engine propeller----- Feather Landing Gear----- Down Flaps ----- Max 25° Rudder Trim----- Set Neutral</p> <p>When certain of making field: Flaps 40° ----- if required</p>

Appendix B

Glossary of Abbreviations.

ATC.....	Air Traffic Control.
CAVOC.....	Ceiling and Visibility OK.
CCTV.....	Closed-circuit television.
ENEMED.....	Aircraft Fuel provider.
ICAO.....	International Civil Aviation Organization.
LMML.....	ICAO-code for Malta.
MATS.....	Malta Air Traffic Services
MIA.....	Malta International Airport
METAR.....	Aviation Routine Weather Report.
NOSIG.....	No Significant Change.
OMAS.....	Office of the Manager Airport Security.
PIC.....	Pilot in Command.
QNH.....	Atmospheric pressure adjusted to sea level
SID.....	Standard Instrument Departure
SOP.....	Standard Operating Procedures.