

# ECCAIRS—SIRS



A safety recommendation of Union-wide Relevance has been updated into the European SRIS Database:

**Recommendation ID:** GB.SIA-2017-0016 **Originator:** United Kingdom - AAIB **Status:** Open

**Global Concern (SRGC)**

**Union-wide Relevance (SRUR)**

**Date issued:** 9/20/2017

**Addressee:** United States - FAA

**Headline:** Software upgrade to help trap the consequences of a data entry error - Boeing 737-86J (C-FWGH), Failure to achieve predicted performance during takeoff, Belfast International Airport, 21 July 2017

**Recommendation Topic(s):** 1. Medical / Human Factors 2. Aircraft operations

**Recommendation Text:** It is recommended that the Federal Aviation Administration, mandate the use of Flight Management Computer software revision U12.0, or later revision incorporating the outside air temperature crosscheck, for operators of Boeing 737 Next Generation aircraft.

**Linked Document(s):** 1. [C-FWGH Special Bulletin S2/2017](#)



recommendationFil  
e.htm